Touchscreen Firmware Upgrade – CTFPAD-2


1. Open ilitekTPTool_v1.0.0.4 , and operate step by step following marked numbers on picture above.
2. [①] search device
3. [   ] increase the TP f/w
4. The attached fw file is the TP f/w needed be upgrade

5. SensorTest_V1.1.0.2 inspect the version of TP f/w

PS: if no display on [   ], that means no device is searched

29.11.2012, CarTFT.com